




- 生产流程
1. 数冲
 2. 去毛刺
 3. 折弯
 4. 焊接
 5. 电镀
 6. 喷涂
 7. 装配

R0.5

JCB